


Tuggeranong Creek: Upper Site

Indigenous Landcare/Jabs

The State of the River

- Site is very eroded with numerous poplar trees and high levels of human-cause erosion and illegal dumping activity
- Walking trail to an Aboriginal axe grinding site now underway
- Site shows a general trend towards a higher level of pH buffering
- Turbidity is generally low
- Salinity steadily decreasing
- Orthophosphates are low and relatively stable
- Dissolved Oxygen levels are too low to sustain fish
- Often goes dry



Current Activities:

- Seasonal monitoring
- Revegetation
- Weed Removal
- Trash Clean -up

Potential Waterwatch Projects:

- Riparian Assessment
- Frog Watch
- Monthly monitoring
- Species list